29

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID: SE Sec.5, T16N-R2W

21602050000

DATE	CREW	MONUMENT	TYPE		
July 1, 2015	Zachariah P. Dechant Gary L. Dechant	Harrison monument wi Kellogg Ave. Down 4". 239' west of driveway			
References:		Bearing	Distance		
1) Set 3/4"x24" iron bar 16' eas	t of Flowering Crab Apple	N41E	46.47'		
2) Existing 3/4"x24" iron bar		South	32.79' (32.77')		
3) Set 3/4"x24" iron bar in field	, down 14"	N36W	54.63'		
4) Existing 3/4"x24" iron bar in lawn, down 3" North GARY I. DECHANT S-1744 CAMP DOLGIAS, WI. DOLGIAS, WI. DOLGIAS, WI. North 35.73' (35.81')					

History of corner establishment since Original Government Survey

In May of 1910, Fred Holden found the original corner and set an iron pipe.

See Reverse Side For Maintenance

Description of corner evidence found:

I found a 3/4"x22" iron pipe, broken and bent at the occupied corner. I replaced the iron pipe with a Harrison marker. The old North-South line fences are gone, but the corner does fit the present occupied line to the North.

Deputy County Surveyor, R.L.S. 1323

Description of corner and witness Witnesses to corner location: William C. Jung	monuments, references a service of the control of t	and accessories used to	o perpetuate the original	# =	3/4"x24"	of this corner: round iron bar, flush ker, down 1"+	Section 9
		Cente	rline of	-	<u>Deerfield</u>	Avenue	• = LOCATION CORNER
SURVEY CONTROL ORDER	Approved:	HARLEY E CO. SU		-32.77	56° E	To center of new power pole	T <u>16</u> N R <u>2</u> wisconsin
Horizontal				# Set	3/4"x24"	round iron bar, flush	
Vertical		WISCONSIN CO	ORDINATE SYSTEM			Ridgevi	lle
Corner Control Sta. Name	t (X)	North (Y)	Elevation (Z		Zone	County of Monroe Wiscons	