. <i>C.</i>
1020

History of original corner establishment:

O. R. Dahl was here in April of 1871. Fred Holden was also here in May of 1907.

Description of corner evidence found:

Set Harrison over existing 14" pipe, the top 6" of the pipe was bent over. When we tried to straighten it, the top broke off. The remainder of the pipe is still there, down 2.5'+.

I, Garold A. Sime , do hereby **28th** day certify that on the \_\_\_\_\_ (evidence) (no evidence) of the \_\_\_\_\_\_\_\_ corner of Section 12, T 18 N. R 2 W Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon. Dated this 22nd day of Jan. 1979. Garold A. Sime, R.L.S. 1261 Crew Chief, County Surveyor's Office

Control Sta. Name

Description of corner and witness mor	numents, references and accessories used to per	petuate the original or re-est	ablished location o	f this corner:		Section 12
ELO. MINES	street signature of the street	Harrison  Ave.	$\frac{32.4}{-0.8} - 0.0$		T_18	= LOCATION CORNER N R 2 WISCONSIN
SURVEY CONTROL ORDER  Horizontal	Approved by: Harley A. Sime County Surveyo					
Vertical	WISCONSIN COORD				Greenfield	
Corner East (X	() North (Y)	Elevation (Z)	Zone	City, Village or Town	Monroe	