(evidence) (no evidence) of the East 1/4

established said corner according to the Wisconsin

Dated this 13th day of May 1983

Fourth Principal Meridian, and I re-

Section 34

Statutes as shown and described hereon.

___. do hereby

1983 I found

Brvan H. Meyer

April

certify that on the

corner of.

	No	118
21	5043	42000

History of corner establishment since Original Government Survey

Fred A. Holden was here in December of 1910 and set an iron pipe off the roots of both original bearing trees.

Description of corner evidence found:

I found a l"x22" iron pipe, $8"\pm$ West of a N-S fence. Also the wire on the fence changes from woven wire to the North to strand to the South.

BRYAN H.

MEYER

SA7127100

TOMAH,

WIS.

OSURVE

Deputy County Surveyor Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: Date: April 15, 1983 - 1:30 P.M. Weather: Windy, P. Cloudy, 45°+. Section 34 Set 3/4"x24" iron bar, flush Witnesses to corner location: Set Holden's 1"x22" Bryan H. Meyer - R.L.S. 1712 Replaced Holden's iron iron pipe as witness pipe with a Harrison Dallas Wilhite at fence corner. marker, up 2"+. flush. FENCE 86.38 20.28 Set 11/4"x24" iron pipe down 14". in field. ■ = LOCATION CORNER Approved: HARLEY A. SIME T_15_N R _4_ W MONROE CO. SURVEYOR WISCONSIN Set 3/4"x24" iron bar. SURVEY CONTROL ORDER k flush. Horizontal WISCONSIN COORDINATE SYSTEM Vertical Town of Portland East (X) North (Y) Elevation (Z) Zone Corner County of ___Monroe_ Control Sta. Name