

U.S. LAND CORNER MAINTENANCE

Corner ID : E1/4 Sec. 5, T16N-R1E
41601052000

DATE	CREW	MONUMENT TYPE -----
September 4, 2013	Zachariah P. Dechant Gary L. Dechant	Harrison and all ties of record destroyed. Reset corner from previous survey points and surveys of record in Section 4. Set TCP in concrete With 6' anchor. Set sign on fence post 2' SW 107' north of creek and 80' west of creek

References:

	<u>Bearing</u>	<u>Distance</u>
1) Set 3/4"x24" hexagon iron bar, down 8"	N36E	22.22'
2) Set 1"x24" iron pipe, down 8", 32' west of creek	N87E	47.72'
3) Set 1"x24" iron pipe, down 8"	S43E	50.32'
4) Set 1"x24" iron pipe, down 8"	S70W	33.18'



