No.	25	

History of original corner establishment:

V 71	EDDL	חחחחנו

I, Harley A. Sime day of June 1975, I found (evidence) (no evidence) of the Section 3, T 16, N, R 2 W Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 4th day of March 19 76.

County Surveyor

Henry Schroeder used this corner in May of 1895.

Henry Schroeder and Hamilton La Rue were at this corner in Sept. of 1897. (In reviewing their notes, it appears that there must have been some confusion over this of corner vidence found:

Accepted the fence corner by parole evidence.

Eary Von Haden, a former resident of the area, stated that this fence corner was the corner. He also said that the fence going North was the line fence and that all of the R/W for the road had come out of Section 3. Von Haden also testified that there used to be a 3-rod road South of the section line to the East. Surveying measurements and field evidence supported Von Haden's testimony. (He made these statements to Harley Sime.)

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: Section 3 Set a Harrison marker at the fence corner, up 5". Witnesses to corner location: W.C. Jung-Crew Chief Line A. Lueck G. Dechant Set 3/4"iron bar 2'from edge of Blazed 7" tree pavement 54.43 w/n&c Line Fence O = LOCATION CORNER 47.15 _T 16 _N Old 3-Rod Town POLE Road W/n&c WISCONSIN Set 3/4"x24" SURVEY CONTROL ORDER Approved: HARLEY A. SIME iron bar Horizontal MONROE CO. SURVEYOR Vertical WISCONSIN COORDINATE SYSTEM City, Village or Town __ Ridgeville_ East (X) North (Y) Elevation (Z) Zone Corner Monroe County of Control Sta. Name