#84

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID : S1/4 Sec. 23 T17N-R2W 21702230020

DATE	CREW	MONUMENT TYPE		
August 17, 2016	Zachariah P.Dechant Gary L. Dechant	Existing Harrison intact. Leaning slightly NE. At four-way fence corner. Bearing trees gone		
References:		Bearing	Distance	
1) Set 3/4"x24" round iron bar, down 12" in field		N60E	23.22'	
2) Set 3/4"x24 round iron bar, down 12" in field		S24E	19.29'	
3)Set 3/4"x24" round iron ba	ar, down 12" in field	S30W	24.06'	
4) Set 3/4"x24" round iron bar, down 12" in pasture		N42W	25.91	

GARY L.
DECHANT
S-1744
CAMP
DOUGLAS, WI

NO SURVENING
29, 2016

I, Harley A. Sime , do hereby certify that on the 16 day of April 19 76 I found (evidence) (no evidence) of the corner of Section 26 , T 17 N, R 2 W, Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 29th day of March 19 77.

History of original corner establishment:

A surveyor was at this corner in November of 1887.

Description of corner evidence found:

Accepted occupied four way fence as the best available evidence after surveying out Section 26.

County Surveyor Approved: HARLEY A. SIME MONROE CO. SURVEYOR

See Reverse Side For Maintenance

