45

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID: SE Sec.10, T19N-R1E

41901100000

DATE	CREW	MONUMENT TYPE					
December 6, 2014	Zachariah P. Dechant Gary L. Dechant	Found Harrison destroyed. Reset from Railroad spikes in bearing trees. All bearing trees are now stumps. Reset corner with 3/4"x6' iron bar inside of 11/4"x3' iron pipe. Set sign 1' north. Now a swampy area.					
References:		Bearing	<u>Distance</u>				
1) Set 3/4"x24" round iron ba	r, 6' SW of two 14" White Pines	N13E	112.32'				
2) Set 3/4"x24" round iron ba	r, 2' south of 8" White Pine	S73E	58.33'				
3) Set 3/4"x24" round iron bar	r, NE of ditch	S49W	71.70'				
4) Set 3/4"x24" round iron bar, at NE end of ditch N80W 123.07' GARY L. DECHANT S-1744 CAMP DOUGLAS, WI October 29, 2015							

History of corner establishment since Original Government Survey

FRED HOLDEN WAS HERE IN SEPT. OF 1903.
KENNEDY MAY HAVE BEEN HERE AT A LATER DATE.

4190110 0000 See Reverse Side For Maintenance

-	established said corner acco Statutes as shown and desc Dated this 3 day of Hary X. T	rding to the Wisconsin ribed hereon. of MARCH 1985.	SET CORNER SW & S'4 THIS FITS EXTREMELY	CORNERS OF SEC HOLDEN'S DISTAN NELL. ALTHOUG CTION IO, DOES	EASTWARD THE TION TO AND CES ALONG TO	HE LINE BETWEEN THE AT A DOUBLED DISTANCE. THE SOUTH LINE OF SEC. A STRAIGHT LINE WITH VCES TO SAID NE É E'14 C	NE È
SURVEYOR FORM NO.	Witnesses to corner location DANNY L. PRAE	:	s and accessories used to perpet		WHITE PINE	this corner: 12" WHITE PINE	Section 10
COUNTY SUR	GARY L. DECHA	INT T	GARY L. DECHANT S-1744 CAMP OUGLAS, W. WORL SURVE	131 1985		STORE ID" DOUBLE 21, 47 WHITE PINE SET HARRISON AT CORNER SET YZ" 1. P. ON NORTH SIDE AS WITHESS.	• = LOCATION CORNER
	SURVEY CONTROL ORE	DER			121	TREES DOUBLE B	T 19 N R 1 E WISCONSIN LAZED WITH R. R. SPIKES SET.
	Corner Corner	East (X)	WISCONSIN COORDINA North (Y)	ATE SYSTEM Elevation (Z)	Zone	County of Mon	OTT (ROE
	Control Sta. Name						