U.S. LAND CORNER MAINTENANCE

Corner ID: E1/4 Sec.30, T19N-R1W

21901302000

DATE	CREW	MONUMENT TYPE
January 13, 2013	Zachariah P.Dechant	Existing Harrison in centerline road

Gary L. Dechant Existing Harrison in cent

References:	Bearing	Distance	
Set 1" iron pipe down 6"	N30W	24.20'	
Set 1" iron pipe down 12"	S40 W	39.59'	
Set 1" iron pipe down 10"	S30E	34.21	
Set 3/4" iron bar down 8"	N12E	32.53	

GARY L.
DECHANT
S-1744
CAMP
DOUGLAS, WI

July 18, 20/3

	No	95	
219	9013	0200	

Dated this 11th day of Jan. 1979.

Garold A. Sime, R.L.S. 1261

County Surveyor's Office

History of original corner establishment:

A. S. Ingalls was at this corner in April of 1873.

Description of corner evidence found:

Replaced existing 3/4" Iron Bar, set by F.W. Zietlow, with a Harrison Mon.

NO. 1	Description of corner and witness	s monuments, references a	and accessories used to perp	petuate the original or re-e	stablished location	n of this corner:		70
FORM	Set Harrison Mon	ument.		i × 1			Section	<u>50_</u>
	Witnesses to corner location:			24" with	Oak, doubl N&C set	e blazed		-
NTY SURVEYOR	D. Dade B. Meyer	GAROLD A.		100 ×		217.82 DN&C in		-
COU		SHAP S-1261 TOMAH, WIS.	A T W O O I	D Harrison	D R	I V E		
		ND SURVE		N&C in pole	power	N&C in power pole	• = LOCATION T_19_N WISCON	R _ 1
	SURVEY CONTROL ORDER Horizontal	Approved `	oy: Harley A. Sin County Surve		·			
	Vertical	rtical WISCONSIN COO		IDINATE SYSTEM		T-t	_	
	Corner Ea	ast (X)	North (Y)	Elevation (Z)	Zone	City, Village or <u>Town</u> <u>Lincol</u> County of <u>Monroe</u>		
	Control Sta. Name					County of		