# 77

## U.S. PUBLIC LAND CORNER MAINTENANCE

**Corner ID**: E1/4 Sec. 21, T19N-R1W

219012120000

DATE February 21, 2015	CREW Zachariah P.Dechant Gary L. Dechant	MONUMENT TYPE  Existing Harrison intact in center line of road, down 2", 69' east of east side of house @ 24986 Briarwood Ave		
References:		Bearing	<u>Distance</u>	
1) Set 3/4"x24" iron bar, down 12" in field		N32E	48.85'	
2) Set 3/4"x24" iron bar, down 12" in field		S36E	61.60'	
3) Set 3/4"x24" iron bar, down 12" in field		S32W	42.94'	
4) Existing 1" iron pipe in line with fence north		North	33.00°	
		A		

Harrison and reference markers 1 & 3 set on straight lines.

GARY L.
DECHANT
S-1744
CAMP
DOUGLAS, WI ZO16

MORELL DOUGLAS, WI ZO16

I, Douglas J. Malliet , do hereby certify that on the 19th day of April 19 78, I found (evidence) (XXXXXXXXX) of the W1/4

Statutes as shown and described hereon.

Dated this 19th day of May 1978.

REGISTERED LAND SURVEYOR, S-1266

History of original corner establishment:

No subsequent history of monument perpetuation since the original U.S. Government Survey.

Description of corner evidence found:

This corner was established at the intersection of a straight line between a Harrison at the NW corner of Sec. 22 and the computed location of the  $W^1_4$  corner of Sec. 27, and the centerline of Airedale Drive. This location agrees well with measurements  $1^1_2$  miles South and the existing North-South fence. However, the distance to the NW corner of Sec. 22 is excessively long. It's my opinion that an error of approximately one chain was possibly made in the measurement of the West line of the NW $\frac{1}{4}$  of Sec. 22.

