No.	101
INU.	

History of original corner establishment:

4 1	80	12	250	0	

I, Lawrence A. Feddersen, do hereby certify that on the lst & 7th day of February 19 79, I found ** (no evidence) of the Northeast corner of Section 36 , T 18 N, R 1 E, Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 22 day of May 1979

Registered Land Surveyor

No subsequent history of monument perpetuation since the original U.S. Government Survey in Monroe County.

Description of corner evidence found:

LAWRENCE

A. FEDDERSEN S-1226

HAMOT

Set Harrison at intersection of road centerlines. Road North & South and East.

Agrees with existing conditions to the North and South.

SURVEYING Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: Section 36 FIELD ENTRANCE hole in top of North end 15" C.M.C.P. Witnesses to corner location: of culvert. 48.12 18" C.M.C.P. Lawrence A. Feddersen COUNTY 1/4" hole in top Mark R. Heidecke of South end of culvert. ST. W. LINE---Harrison O = LOCATION CORNER Monument hole in top of South end of culvert. T_18_ N WISCONSIN PLACED SURVEY CONTROL ORDER COUNTY SURVEYOR'S Horizontal SIGN 6-18-87 Vertical WISCONSIN COORDINATE SYSTEM XXXXXXXXXXXXXX Town Byron East (X) North (Y) Zone Elevation (Z) Corner County of __Monroe Control Sta. Name Wisconsin