

Sec 4 & 5
T₁₆ R_{1E}

Retraced section line N + S, between secs 4 and 5 of
Town 16 Range One East for C. L. S. of Indian Creek
the $\frac{1}{4}$ corner being a lost corner.

Commenced at Sec post corner of sections 4, 5, 8 and 9
Randomed North on bearing of $S. 42^{\circ} E$ at 180 rods set
Temporary $\frac{1}{4}$ post thence north intersecting Town Line 61 feet
East of sec corner. distance 180 10 links

Detected $6^{\circ} 4' E$

At 180 10 S set $\frac{1}{4}$ post Bearing true Rod 10 10 in 3348

Rod " 6 " 310 $\frac{1}{2}$

At Sec corner on Town Line found old bearing true made new survey

Rod 8 in 7228 52 links

Rod " 6 " 3348 58 $\frac{1}{2}$ "

Recorded this 10th day of May 1897

Hamilton Lee Reed
Co Surveyor