



Survey made Nov-27-28+29 1906
by direction of Bertha Frohmader
Sworn assistants

Chairmen $\&$
Adam Milbauer
Ben Frohmader

Flagmen
Lauris Frohmader
Robt Milbauer

Lines run by both fore and back sights

all random stakes corrected
on NW 1/4 of SE 1/4 there is a fence running north and south
standing 1 1/2 rods East of corner #22 and one rod East of corner
#23 and is somewhat crooked

Field Notes

- NE Sec Cor both original B then standing
- SE " " Bad Stump 10 S 15-E 502 Original
- N 1/4 " " Stps both old B then "
- S 1/4 " " reestablished in line
- C1 Stake
- #3 "
- #7 Wo 14 S 48 W 38
- #9 Stake
- #10 fo 18 S 63 1/2 E 39
- #13 1 in iron pipe at corner
- #18 26 No. Pine 10 S 28 W 19
- #19 27 Wo 10 N 62 1/2 E 5 1/2
- #20 28 Bro 8 S 32 W 8 1/2
- #21 29 Stake
- #22 30 "
- #23 31 Iron "

Dated January 15th 1907
Paul A. Holden
Co Surveyor