



Survey made April 5<sup>th</sup> 1907  
by direction of Herman Reunit  
Sworn assistants

Chairmen

Otto Bartels  
F A Holder

Flagmen

Paul Benevickow  
Herman Reunit

Careful Chaining on North Line of section develops a shortage from original field notes of 2 chains + 18 links which I have divided in proportion between fractional 40 and the one next East

Chaining on south line agrees exactly with foot field notes  
field notes

N-E Sec Cor W 24 N 83 W 40

NW " " Stone at corner placed by Paul Benevickow when all bearings stood

SW " " Corner maintained since bearing trees stood Original

N 1/4 " " Tamaroc 12 S 33 W 86 (established in line)

S 1/4 " " W 10 S 10 E 4 Original

E 1/4 " " B 12 N 88 W 11 " 1908

C' W 12 N 42 E 14 1/2 1908

# 2 W 24 S 63 W 15 3

# 4 Stake

# 6 Hick 4 West 127

# 9 Red 5 N 15 E 6 1/2 1908

# 10 B 24 S 1 E 86 1908

Recorded April 6<sup>th</sup> 1907

Paul A Holder

Co Surveyor