U.S. LAND CORNER MAINTENANCE

4) Set 11/2"x24" iron pipe, down 6"

Corner ID: S1/4 Sec.18, T15N-R1W

21501180020

16.76

DATE	CREW	MON	UMENT TYPE
November 11, 2013	Zachariah P.Dechant Gary L. Dechant	Existing TCI	monument at fence corner
References: 1) Set 1½"x24" iron pipe, down 6" 11' SW of 30"White Oak bearing tree of 1997		Bearing N65E	Distance 13.38'
2) Set 1½"x24" iron pipe, down 6"		S12E	15.81'
3) Set 1½"x24" iron pipe, down 6"		S50W	11.30°

N41W

Corner

Control Sta, Name

County of MONROE