Lawrence A. Feddersen do hereby

corner of Section 15, T 18, N, R 1E Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin

Dated this 30 day of Nov. 1981

Statutes as shown and described hereon.

Registered Land Surveyor

19.81_.I found

certify that on the _____

of September

No	46
13171	

History	z of	corner	actablic	hmant si	ince Ori	ginal	Government	Survey
THSTOLY	נט ץ	corner	establis	ument si	nice Ori	Killgi.	Government	ourvey

41801100020

Section 15

None

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Description of corner evidence found:

Set Harrison half way on straight line between the Northeast corner and the Northwest corner.

Two-way fence corner was not used as fence had many bends and used a tree as the corner. Adjacent property owners North and South, both agreed the fence was not correct.

DUNTY SURVEYOR FORM NO. 1

Witnesses to corner location:

Nail/washer in
blaze and painted
orange in 5½"

Thomas Mangene double white oak

Timothy Fisher

Approved: HARLEY A. SINE

MONROE CO. SURVEYOR

dead red oak

The in 5½"

The white oak

set Harrison Monument

set

nail/washer in

blaze and painted

orange in 5½" white oak

-Fence

asher in and painted o = LOCATION CORNER

T 18 N WISCONSIN

 $R_{\rm e}^{\rm 1E}$

SURVEY CONTROL ORDER

11-01-02-1

HUITZUITAI					
Vertical					
	East	t (X)	North (Y)	Elevation (Z)	Zone
Corner			:		.*
Control Sta. Nam	ne				

XXXXXXXXXX	Town _C	£	Byron	
•		•		

County of Monroe