U.S. LAND CORNER MAINTENANCE

Corner ID: SE Sec.19, T19N-R1E

41901190000

DATE	CREW	MONU	MENT TYPE
November 2, 2013	Zachariah P.Dechant Gary L. Dechant	11/4" on NE side of s	over Existing Stone (+), stone, PK nail 2' west & 2' north uckley Ave & Brunswick Ave
References: 1) Set 1"x24" iron pipe, down between wildlife signs	n 6"	Bearing N43E	Distance 55.31'
2) Set 1"x24" iron rod, down	6"	S44E	47.20°
3) Kennedy's existing 2" cap Straightened, up 12"	ped iron pipe, bent & leaning	South	24.55'
4) Existing 1"x24" iron pipe,	south r/w, 40 west of section line	SW	46.14°
5) Existing ¾" round iron bar	on section line	west	40.00°

COORDINATES:

GARY L.
DECHANT
S-1744
CAMP
DOUGLAS, WI

				No	٠		91				
4	1	9	П	1	1	9	П	П	П	П	П

I. William	C. Jun	g	do hereby
certify that on the	eight	eenth'	day
recrify that on the of	of the	19_50	I found uthwes
corner of Secti	on 20		<u>г 19 · N,</u>
R L Fourth	Principal	Meridian,	and I re-
established said cor Statutes as shown a		_	
Dated this 27th			
William			
	U	•	
William C.	Jung -	R.L.S	. 1323

History of corner establishment since Original Government Survey

Fred Holden set a stone at this corner in June of 1902. Kennedy found this stone in his survey of the late 1930's. Bergman also found this stone in his survey of July, 1954.

Found 6"x9"x17" limestone with cross, down 5", resting on top of a smaller stone. "Left" stone in and set a 1½"x30" round iron bar on the Northeast side of stone as witness. Set nails and caps 2' North and West of stone. (*Also found dead 16", partially petrified pine to Northeast. This tree fits Holdens bearing and distance. It had been hacked back previously, and shows old scribings - S.)

Title Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: Section __20 Double Oak -Found 6"x9"x17" Limestone N With Cross Witnesses to corner location: William C. Jung WILLIAM Chuck Dade C. JUNG S-1323 Center Of St. 52.73 TOMAH, O = LOCATION CORNER Nail & Cap Found Kennedys Reference Iron Pipe Bent in Power Pole NOTE: & Leaning To The Northwest T 19 N R 1 E All Trees Double Blazed With Nails & Caps Set Approved: HARLEY A. SIME WISCONSIN MONROE CO. SURVEYOR SURVEY CONTROL ORDER

Horizontal				·	
Vertical		WISCONSIN COORDINATE SYSTEM			
Corner	East (X)	North (Y)	Elevation (Z)	Zone	
Control Sta. Name					

Town of Scott	
County of Monroe	
Wisconsin	