No.	_24

History of original corner establishment:

				-		
21	90	14	02	200	12	

I, Harley A. Sime , do hereby certify that on the 2nd day of June 1976, I found (evidence) (no evidence) of the N1/4 corner of Section 11 , T19 N, R 4 W, Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 15th day of March 1978.

Harley Sime

County Surveyor

Fred Holdon re-established this corner in November of 1904. He set stone at the corner.

Holden was also at this corner in Oct. of 1909.

Description of corner evidence found:

Found and accepted a stone as the corner. Also found iron bar, angle iron, and wood stake beside stone.

Witnesses to corner location:  D. Mælliet-Crew Chief  A. Lueck  HAF  S  S TO	o=Set 3/4" iron bar by last standing fence post  •=Existing 3/4" iron bar  NLEY A.  I M E  355  DMAH, WIS.	Found stone end of stone of angle iron there is a voice of stone is down 3".	of this corner:  Nort  DRIVE  with iron bar at se, also with wester on over middle of sevond stake beside town 14.5", Existing and angle iron do spike over middle	outh ly point tone. he stone. iron wn 12".
Horizontal	*			
Vertical	WISCONSIN COORDINATE SYSTEM	Zana	City, Village or Town	Little Falls
Corner East (X)	North (Y) Elevation (Z)	Zone	City, visiage of fown	
Control Sta. Name		**************************************	County of	Monroe