No	76
NO.	 

History of corner establishment since Original Government Survey

41801202000

I, Bryan H. Meyer, do hereby certify that on the 18th day of August 19.83, I found (evidence) of the East 1/4 corner of Section 20, T.18. N, R.1. E Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 23 day of Dec. 19 83.

Buyn H. Meyer

Deputy County Surveyor

Duane Marten was here in 1969 and set a ¾" iron Bar.

Description of corner evidence found:

Found Mr. Marten's iron bar and replaced it with a Harrison Marker.



Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: Crew: Meyer, Wilhite Section 20 Maple Date: August 18, 1983 Weather: Humid, MOSQUITOES!!, 90°+. Witnesses to corner location: Maple Bryan H. Meyer Dallas Wilhite Set 3/4" iron bar Replaced ¾" iron bar in natual mound. = LOCATION CORNER with Harrison Marker. APPROVED: Harley A. Sime T\_18\_ N R 1 E Monroe County Surveyor The three bearing trees WISCONSIN are double blazed; distances SURVEY CONTROL ORDER are to nails in hacks in the The bearings shown are sides of the trees. hand compass bearings. Horizontal Vertical WISCONSIN COORDINATE SYSTEM Town of Byron North (Y) Zone East (X) Elevation (Z) Corner County of Monroe Control Sta. Name