Schroeder was at this corner in April of 1893.

No.	47

History of original corner establishment:

21804090000

I. William C. Jung \_\_\_\_\_ do hereby 31st day certify that on the of \_\_\_\_October \_1978\_, I found (evidence) (no evidence) of the NE corner of Section 16 T 18 N. R 4 W, Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 5th day of Jan. 1979.

William C. Jung, R.L.S. 1323

Crew Chief, County Surveyor's Office

Description of corner evidence found:


Found original bearing tree down. Measured back from tree with distance and bearing. Found rotted remains of old stake. Replaced stake with Harrison.

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner: Set Harrison Monument; made dirt and rock mound around Harrison.

Witnesses to corner location: W. Jung G. Dechant TOMAH

East (X)

(All trees double blazed with N&C's set)



	Section	16		
				•
ļ			 	
	<u> </u>			
	<u> </u> 		!    -  -	
	<b></b>			
	= LOCATI	ON COR	NER	
-	N	R_	<u>4</u>	_ W

WISCONSIN

SURVEY CONTROL ORDER

Corner Control Sta. Name

Horizontal

Vertical

Approved by: Harley A. Sime County Surveyor

WISCONSIN COORDINATE SYSTEM North (Y) Zone Elevation (Z)

Set hexagon iron bar where original bearing tree was standing. Tree is now down; it fell to the SW. The tree is 30" in diameter. Dug out old rotted blaze down to original blaze area. Set rocks around the hexagon iron bar.

City, Village or <u>Town</u>	Little	Falls	
County of	Monroe		