



Survey made April 10th + 11th 1908
 by direction of Elda Noble
 Survey Assistants

Chairmen
 John Nordick
 Robt Witt

Flagmen
 Robt Williams
 Richard "

Armen
 Al Abbott
 Raleigh Cooper

Field Notes

- NE Sec Cor reestablished set Buggy axle at corner
- NW " " Bas 10 S ~~137~~ ^{25.9} 137 Original
 Pine stump 12 N40E 132 "
- SE " " Bo 7 S41E 77 " remains other tree and old stk Pt
- SE " " Original by remain all B then set from stake at corner
- S 1/4 " " " " " "
- E 1/4 " " reestablished in line
- W 1/4 " " " " " "
- C1 1 1/2 in Pipe at corner
- # 9 Buggy axle at corner
- # 11 Iron stake at corner
- # 13 Stake
- # 14 "
- # 15 Jo 20 S70 1/2 W 28 1 1/2 in Pipe at corner
- # 16 Iron spike at corner
- # 17 Jo 10 N81E 6 1/2 1 1/2 in pipe at corner
- # 18 26 " " "
- # 19 27 Stake

Recorded April 11th 1908
 Paul A Holden
 Co Surveyor