

State of Wisconsin  
 Monroe County J.B.S.

Sec 22 | Sec 23  
 1/4 part

I hereby Certify that for H B Johnson  
 I have surveyed, and from original bearings, reestablished  
 the East 1/4 part of Section 22 Township 18 North Range 1 West  
 from White pine stump about 10 in diameter. Showing B.T. plain.  
 being facing North West. set course N 39° W at 19 links set  
<sup>with compass over pin</sup>  
 Pin, thence course S 63° W at 28 links stuck pin in White pine stump  
 too much decayed and burnt to show marker. removing the  
 sod under compass disclosed stake hole immediately under pin  
 traced the same down size and shape of pointed stake  
 rotted vegetable mold (no timber) to depth of 20 inches.  
 set in old stake hole 1 1/2 in round Iron bar and made  
 new bearings to 6 S 14° E 5 1/2 links to 6 S 23° W 97 links

Witness my hand this 10th day of September a.d. 1908

Frederic A. Holden

Surveyor Monroe Co Wis