#1

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID: NE Sec.1, T15N-R1W

21601360000

DATE March 8, 2019	CREW Zachariah P.Dechant Gary L. Dechant	MONUMENT TYPE Existing Harrison intact in down north-south fence. 35' east of 6' deep ravine. Reset sign 1' south.		
References:		Bearing	Distance	
1) Set 24" section of steel fence post (T-post)		N8E	18.76'	
2) Set 24" section of steel fence post		S56E	9.05'	
3) Set 24" section of steel fence post, 5' NE of 8" Black Cherry		S67W	17.26'	
4) Set 24" section of steel fence post, between small stones		N18W	29.18'	



		_
Garv	L.	Decha

; do hereby 4th certify that on the _____ of ____August 19 87, I found (evidence) Section 1 corner of R 1 W Fourth Principal Meridian, and I reestablished said corner according to the Wisconsin Statutes as shown and described hereon.

Dated this 7th day of August 1987.

Reg. Land Surveyor, S-1744

History of corner establishment since Original Government Survey

Fred Holden was here in April and May of 1901.

See Reverse Side For Maintenance

Description of corner evidence found:

Set corner in North-South fence intersecting with projected fence from the West. This location fits other corners along the 4th Prime Meridian extremely well as well as corners to the West.

Witner Day	iption of corner and with	ness monuments, references and	I4" DOUBLE WHITE OAK HARRISON IN SMALL STON PILE SIGN N. SIDE HARR	25.00'	8" DOUBLE BOX ELDE	GARY L. DECHANT S-1744 CAMP DOUGLAS, WI	Section 1 • = LOCATION CORNER T 15 N R WISCONSIN
	JRVEY CONTROL ORDI	ER			4" HICKORY		
Ve	Vertical			WISCONSIN COORDINATE SYSTEM		Wellington Wellington	
	Corner	East (X)	North (Y)	Elevation (Z)	20116	County of Monroe	
	Control Sta. Name						and the second s