62

U.S. PUBLIC LAND CORNER MAINTENANCE

Corner ID: S1/4 Sec.13, T17N-R1W

21701130020

DATE	CREW	MONUMENT TYPE	
November 12, 2018	Zachariah P. Dechant	Harrison intact at fence corner. S	et sign 1' north.
	Gary L. Dechant		_
References:		Bearing	Distance
1) Set 3/4" round iron bar, do	wn 4",	N50E	24.30'
2) Set 3/4"x24"round iron bar, down 4"		S80E	16.81'
3) Set 3/4"x24" round iron bar, down 10"		S32W	13.45'
4) Set 3/4"x24" round iron bar, down 4", 4' SE of 16" Black Oak		N65W	17.80'

GARY L.
DECHANT
S-1744
DOUGLAS, WI

DOUGLAS, WI

DOUGLAS, WI

DOUGLAS WI

DOUG

CERTIFICATE			

CERTIFIED LAND CORNER

	1 100	
Jo-	6	
νn	The second secon	

L Gary L. Dechant	, do hereby
certify that on the 3: of June	rd day 19 <u>86</u> , I found
(evidence) (no reidence) of the corner of Section	he S ¹ 4 13 T 17 N
R 1 W Fourth Principal	Meridian, and I re
established said corner accord	ling to the Wisconsin
Statutes as shown and describ	bed hereon.
	N20

Hary L. Dechart

Registered Land Surveyor, 1744

History of corner establishment since Original Government Survey

Fred Holden was here in October of 1908.

Description of corner evidence found:


We found an unrecorded iron pipe and accepted it as the corner as it fit other section data extremely well.

See Reverse Side For Maintenance

Description of corner and witness monuments, references and accessories used to perpetuate the original or re-established location of this corner:

Witnesses to corner location:

Gary L. Dechant	
David Madison	



Section 13

WISCONSIN

SURVEY CONTROL ORDER

(Trees double blazed with N&C's set)

City, Village or Town	Tomah
County of	Monroe

SSI744 CEAMP DOUGEAS, WI